DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/02/2015 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL		TIPLE CONSTRUCTION NG 01		(X3) DATE SURVEY COMPLETED R 08/28/2015	
		155329	B. WING					
NAME OF PROVIDER OR SUPPLIER				ST	REET ADDRESS, CITY, STATE, ZIP CODE	1 00/	20/2015	
					02 N LESLEY AVE			
ROSEWALK VILLAGE				IN	INDIANAPOLIS, IN 46219			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	CTIVE ACTION SHOULD BE NCED TO THE APPROPRIATE		
{K 000}	INITIAL COMMENTS		{K (000}				
	INITIAL COMMENTS A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 07/09/15 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 08/28/15 Facility Number: 000222 Provider Number: 155329 AIM Number: 100274950 At this PSR survey, Rosewalk Village was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2. This one story facility was determined to be of Type V (000) construction and fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors and in all areas open to the corridor. Battery operated smoke detectors are installed in all resident sleeping rooms. Smoke detectors hard wired to the fire alarm system are additionally installed in resident sleeping rooms 201 through 211. The facility has a capacity of 161 and had a census of 158 at the time of this visit. All areas where residents have customary access were sprinklered. All areas providing facility services were sprinklered except two detached wooden sheds providing facility storage.							
LABORATORY	 	SUPPLIER REPRESENTATIVE'S SIGNATUR	lF		TITLE		(X6) DATE	

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that

other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.